

Figure 3-14. M68000

Parts Not Suitable

For Additional

End-Of-Life Prod



ADDENDUM TO MC68341 Integrated Pro

April 19, 1995

This addendum to the initial release of the MC68341 text, plus additional information not included in the or is maintained on the AESOP BBS, which can be (512)891-3650. Configure modem for up to 14.4Kbps should support VT100 emulation. Internet access [129.38.233.1] or through the World Wide Web at http

1. Signal Index

On page 2-4, Table 2-4, the QSPI serial clock QSCL 2-5, FC3/ \overline{DTC} is an output-only signal.

2. Operand Alignment

On page 3-9, last paragraph, change the first two lines (instructions) to be word-aligned. That is, word and long-word operands do not have to be long-word aligned.

3. \overline{WE} on Fast Termination

On page 3-17, Figure 3-6, \overline{UWE} and \overline{LWE} do not as

4. Write Cycle Timing Waveforms

On page 3-25, the M68300 write cycle timing diagram \overline{LWE} . On page 3-28, the M68000 write cycle timing diagram \overline{CSx} , $\overline{UDS/LDS}$, and $\overline{UWE/LWE}$. Replace these figures

5. Additional Note on MBAR Decoding

Add to the CPU Space Cycles description on page 3-10 a block from \$3FF00-3FFFF to the SIM module. An instruction for any access to this range, but selection of specific

Accesses to the MBAR register at long word \$3FF0 cycles. Users should directly access only the MBAR LPSTOP broadcast access to \$3FFFE. The remainder should not be accessed.




Figure 3-12. M68300

Table 4-2. System Frequencies

Y	CLKOUT (kHz)				VCO (kHz)
	W = 0				W = 0
	Z = 0		Z = 1		Z = x
	X = 0	X = 1	X = 0	X = 1	X = x
0	16	33	131	262	524
1	33	66	262	524	1049
2	49	98	393	786	1573
3	66	131	524	1049	2097
4	82	164	655	1311	2621
5	98	197	786	1573	3146
6	115	229	918	1835	3670
7	131	262	1049	2097	4194
8	147	295	1180	2359	4719
9	164	328	1311	2621	5243
10	180	360	1442	2884	5767
11	197	393	1573	3146	6291
12	213	426	1704	3408	6816
13	229	459	1835	3670	7340
14	246	492	1966	3932	7864
15	262	524	2097	4194	8389
16	279	557	2228	4456	8913
17	295	590	2359	4719	9437
18	311	623	2490	4981	9961
19	328	655	2621	5243	10486
20	344	688	2753	5505	11010
21	360	721	2884	5767	11534
22	377	754	3015	6029	12059
23	393	786	3146	6291	12583
24	410	819	3277	6554	13107
25	426	852	3408	6816	13631
26	442	885	3539	7078	14156
27	459	918	3670	7340	14680
28	475	950	3801	7602	15204
29	492	983	3932	7864	15729
30	508	1016	4063	8126	16253
31	524	1049	4194	8389	16777

6. Additional Notes on CPU Space Addressing

On page 3-31, Figure 3-16, the BKPT field for the Breakpoint Acknowledge LEV and the T bit is on bit 1. The Interrupt Acknowledge LEV is on bit 0.

7. Breakpoints

On page 3-31, the last paragraph implies that either a breakpoint can be used to insert an instruction. As a result, a breakpoint can be used to insert an instruction on the bus.

8. Interrupt Latency

Add to the Interrupt Acknowledge Bus Cycles section: The latency of the prefetch of the first instruction in the interrupt handler is 108 clocks (using 2-clock memory and autovector termination). (DIVS.L with worst-case <fea>) = 108 clocks worst case. For a shorter interrupt response time the latency can be reduced by the use of longer instructions (specifically DIVS.L, DIVU.L, M).

9. Interrupt Hold Time and Spurious Interrupts

Add to the Interrupt Acknowledge Bus Cycles section: The interrupt is asserted until the corresponding IACK cycle; otherwise, the interrupt may be ignored entirely. This is also true for level sensitive interrupts using either the \overline{AVEC} signal or the AVEC register, since the interrupt is on the IMB if the external interrupt at that level has been asserted. Level sensitive only have to be held a minimum of 1.5 clocks - see the PIR REGISTER (PIR).

Note that the level 7 interrupt is also level sensitive, and the level 7 interrupt is unique in that it cannot be masked - another IACK cycle by negating IRQ7 and reasserting, even though the level 7.

10. Typos in IACK Cycle Timing Waveform

On page 3-38, Figure 3-21, the text "VECTOR FROM 8-BIT PORT" should be on D15-D8. The response is the significant byte of the data port.

11. Additional Note on Internal Autovectoring

Add to the Autovector Interrupt Acknowledge Cycle section: The autovector is autovectored either by the AVEC register programming or by the interrupt started and terminated internally. The interrupting device is the resulting operation is undefined.

12. Additional Notes on Retry Terminations

On page 3-42, Table 3-4: When \overline{HALT} and \overline{BERR} are asserted, the bus cycle, relative timing of \overline{HALT} and \overline{BERR} must be considered.

stable value, the 328*TCLKIN delay is counted down, and a delay. For external clock mode without VCO, the 328*TC are recognized. See note for page11-3 for more POR in

On page 4-6, first paragraph, change the first sentence to bus masters on the MC68341 to access the inter-module

20. Additional Note for External Clock

On page 4-9, Table 4-1, External Clock Mode with PLL:
falling edge of the EXTCLK input clock. Maximum skew
signals is specified in the Section 12 Electrical Character

21. External Clock Mode Operation

The next-to-last paragraph on page 4-11 incorrectly states that the system frequency in external clock mode. In external clock mode, by selecting either EXTCLK or EXTCLK/2 as reference clock, the clock divided by 2 is used both for CLKOUT as well as the feedback divider. When VDD=0, resulting in an initial processor operating frequency of 0.

For applications using external clock mode, the 32KHz clock should be very clean when the 32KHz oscillator is used - ground EXTAL and CLK should be very clean when the 32KHz oscillator is used. Fast edge rates may result in coupling to the adjacent XTAL pins.

22. Recommended XFC Capacitor Va

On page 4-12, third paragraph, and page 11-2, last paragraph, the reference to 0.1μF applies specifically to crystal mode operation. For detector reference frequencies > 1MHz start with a capacitance of 0.1μF. At 16.0MHz the recommended XFC capacitance is approximately 0.01μF, the standard value available.

23. CLKOUT and VCO Frequency Pro

On pages 4-13 and 4-14, the column for W=1:Z=0:X=1 column is 2x the frequency in the X=0 column immediate ing pages. Note that although a complete table is shown frequency limits must be observed when programming the cy (CLKOUT) of 25.16MHz can be selected with W:X:Y:Z. However, programming W:X:Y:Z=1:0:47:1 to achieve the quency of greater than 100MHz, which is outside the sp

24. Additional Note for Global Chip S

On page 4-16, section 4.2.4.2: When operating as a global master, the master can read from either the MBAR or to internal peripheral module registers.

On page 3-57, Figure 3-34. Power-Up Reset Timing Diagram shows that the internal control signals, and can begin toggling as soon as the device is powered up and operating. For crystal mode and external clock with VCO

38. Additional Notes on DMA Feature

In the feature set listed on page 6-1, bullet six is "Oper:fers". This packing is for transfers between different por e.g. Byte <> Word transfers. The DMA controller does n problem of residual bytes left in the controller when a ch

39. Additional Note on Internal Reque

Add to the Internal Request Generation section on page Ex are not active as outputs during transfers. DONE_x is operation if asserted - pull up if not used.

40. Additional Note on DMA Transfer

Add to the External Request Generation section beginni synchronization and IMB bus arbitration activity before sation will preempt the next CPU bus cycle if it is recogn bus cycle, unless the current cycle is not the last cycle o Operand transfers and RMC read/write sequences are i not be arbitrated from the CPU until the complete opera sizing results in multiple bus cycles.

For a \overline{DREQx} assertion during an idle bus period, bus st: clock falling edge which \overline{DREQx} is recognized on. Th \overline{DREQx} is recognized on to the falling edge that \overline{AS} for table for various memory speeds.

DREQ Latency (Clocks) vs. Bus

Access Type	Maximum \overline{DREQx}		
	16-Bit Bus Clocks/Bus Cyc		
	2	3	4
Longword	7	9	11
RMC (TAS)	10	12	14

41. Additional Note on Burst Transfer

On page 6-5, replace the 2nd paragraph of 6.3.2.1 Ex: negated one clock before the end of the last DMA bus c being generated. Also, \overline{DREQx} must be negated two cloc an idle clock between that transfer and the following CP

42. Additional Note on Cycle steal DM

Add to the External Cycle Steal Mode description on p: ently. However, for some 2-clock accesses using cycle : incomplete overlap of the DMA transfer with internal IM single address 2-clock transfers and 2) dual address tra completely overlapped for all other cases.

Table 4-2. System Frequencies from 3

Y	CLKOUT (kHz)				VCO (kHz)
	W = 0				W = 0
	Z = 0		Z = 1		Z = x
	X = 0	X = 1	X = 0	X = 1	X = x
32	541	1081	4325	8651	17302
33	557	1114	4456	8913	17826
34	573	1147	4588	9175	18350
35	590	1180	4719	9437	18874
36	606	1212	4850	9699	19399
37	623	1245	4981	9961	19923
38	639	1278	5112	10224	20447
39	655	1311	5243	10486	20972
40	672	1343	5374	10748	21496
41	688	1376	5505	11010	22020
42	705	1409	5636	11272	22544
43	721	1442	5767	11534	23069
44	737	1475	5898	11796	23593
45	754	1507	6029	12059	24117
46	770	1540	6160	12321	24642
47	786	1573	6291	12583	25166
48	803	1606	6423	12845	25690
49	819	1638	6554	13107	26214
50	836	1671	6685	13369	26739
51	852	1704	6816	13631	27263
52	868	1737	6947	13894	27787
53	885	1769	7078	14156	28312
54	901	1802	7209	14418	28836
55	918	1835	7340	14680	29360
56	934	1868	7471	14942	29884
57	950	1901	7602	15204	30409
58	967	1933	7733	15466	30933
59	983	1966	7864	15729	31457
60	999	1999	7995	15991	31982
61	1016	2032	8126	16253	32506
62	1032	2064	8258	16515	33030
63	1049	2097	8389	16777	33554

NOTES:

- Some W/X/Y/Z bit combinations shown may select a CLKOUT frequency. See Table 11 Electrical Characteristics for CLKOUT and VCO frequencies.
- Any change to W or Y results in a change in the VCO frequency.

25. Additional Note on PORTA/B Output

Add to the External Bus Interface Operation description after the S4 falling edge for the internal write to the PORTA/B registers at roughly the same time DS negates for the data specified in the Electrical Specifications.

26. RTC Memory Map

The RTC register offsets shown on page 4-21 are incorrect. Addresses within the RTC can be accessed as either byte or word. The offset \$0CE. Note that RTC registers marked S/U are reserved in user mode.

ADDR	FC	15	8
0C0	S		RTC INTER
0C2	S/U	MINUTES (MIN)	
0C4	S/U	DATE	
0C6	S/U	MONTH	
0C8	S	RTC CONTROL/STATUS (RCR)	
0CA	S/U	MINUTES ALARM (MINA)	
0CC	S/U	DATE ALARM (DATEA)	
0CE	-	RESERVED	

27. MBAR Register Reset Values

On page 4-22, the reset values for MBAR bits 31-12 are

28. MBAR AS7 Bit and IACK Cycles

On page 4-23, the second code sequence initializes the address decode for the internal 4K register block from register 0. This prevents the register block decode of \$FFFFFFxxx from incorrectly possibly corrupting the vector number returned. Normal operation is not affected by this change.

Early versions of the MC68330 User's Manual (original Rev. 1 releases) did not show AS7 set. Code which was checked for this problem when porting to the MC68330 and/or MC68340.

29. Additional Note on VCO Overshoot

On page 4-30 place the following note under the Y-bits:

A VCO overshoot can occur when increasing the operating frequency. The effects of this overshoot can be controlled by:

1. Write the X bit to zero. This will reduce the previous frequency.
2. Write the Y bits to the desired frequency divided by 2.
3. After the VCO lock has occurred, write the X bit to one to increase the clock frequency to the desired frequency.

Steps 1 and 2 may be combined.

30. RCCR Initialization

Add to the RCCR description on page 4-41: the RCCR register is initialized to an arbitrary value on initial powerup of the RTC. Calibrate the RCCR before beginning the calibration process, since RTC operation is not possible in reserved - on current silicon it always reads 0, and should be initialized.

31. RCCR Typos

On page 4-42, delete the first description for RCD4-RCD7.

32. MONTH Register Range

The valid range for the MONTH register on page 4-43 is 1 to 12, corresponding to December.

33. SIM41 Example Code

On page 4-49, about mid-page, change "MOVEQ #8, D0" to "MOVEQ #8, D1".

34. Bus Error Stack Frame

On page 5-61, in the next-to-last paragraph, delete "(the stack pointer and the SSW is located at SP+12)". The stack space allocated for the internal count register and SSW remains the same. The stack counter location SP+10 and SP+12 will contain invalid data. For the four-word frames, look at the first nibble of the faulted exception frame, and \$2 for the six-word frame.

35. DSO Timing

On page 5-71, Figure 5-23, DSO transitions one clock later.

36. Typo on BDM RSREG Command

On page 5-77, Section 5.6.2.8.6, RSREG register bit #8.

37. IPIPE Timing

On page 5-88, Figure 5-29 shows the third IPIPE assertion. Add an additional 0.5 CLKs. IPIPE transitions occur after the fall of the clock.

* Timer register offsets from timer1 ba			
IR	EQU	\$4	interrupt regist
CR	EQU	\$6	control register
SR	EQU	\$8	status register
CNTR	EQU	\$A	counter register
PRLD1	EQU	\$C	preload register
COM	EQU	\$10	compare register

On page 8-27, change the last code line from "CLR.W S TC interrupt status bits are cleared by writing a "1" to cleared without affecting the other bits.

On page 8-28, second code line down, the "MOVE.W # initialized vector - change the \$0F to a user-definable v just past mid-page.

61. MC68341 BSDL File

An electronic copy of the BSDL file for the MC68341 is n of this document for information on accessing AESOP.

62. Additional Note on Oscillator Lay

Add to the Processor Clock Circuitry (page 11-1) and S short connections and place external oscillator compone through or near the oscillator circuit, especially high fre note above on DREQ1 and serial oscillator for page7-5). a separate trace for ground to the oscillator so that it do

63. Recommended 32KHz Oscillator (

On page 11-2, Figure 11-2, a 10M resistor can be subst




Figure 11-2. Sampl

64. SRAM Interface

The SRAM interface shown in Figure 11-5 on page 11-4 LWE do not assert for 2-clock writes.

43. Additional Note on Cycle Steal

For the external cycle steal mode description on page held off until after the channel is started. If DREQx is alr the channel start bit, an internal DREQx assertion is gen to start.

44. DREQx Negation on Burst

On page 6-8, Figure 6-5, and on page 6-10, Figure 6-7, (one clock earlier than shown) to prevent another DMA 6-5 on Burst Transfer DREQx Negation.

45. DREQ Assert Time

On page 6-21, Figure 6-13: The second DREQx assertion antee recognition on 2 consecutive clock falling edges. 1 should be deleted.

46. Fast Termination and Burst Requ

On the last paragraph of page 6-21, delete the referenc incorrectly - it actually shows operation with fast termina second DREQx signal should be held for 2 consecutive 1 clock edge. Note 1 of Figure 6-14 should be deleted.

47. Typo in DAPI

On page 6-26, for DAPI = 1, the DAR is incremented ac

48. Additional note on DMA limited ra



On page 6-27, in the BB-Bus Bandwidth Field: The DMA is the bus master (each channel has its own counter). relinquish the bus before completion of the active count Higher priority requests could come from 1) the other CPU32 core (if either the interrupt mask level in the SR channel's ISM level), or 3) an external bus request. Wh releases the bus, and the "idle" count increments regard

49. Configuration Error

The Configuration Error description paragraph at the top error results when 1) either the SAR or DAR contains a in the CCR, or 2) the BTC register does not match the la

50. Additional Note on DMA Interrupt

Add to the Interrupt Register description on page 6-31: W interrupt level, channel 1 is higher priority than channel 1



Case 86

65. Corrections to 8/16-Bit DMA Cont

On page 11-10, the logic driving \overline{OE} on the 74F245 in Figure 11-14 is shown. Although not detailed, the byte enables for the memory block are shown. Attention between the upper and lower bytes of the data bus is shown.




Figure 11-14. Circuit For Interfacing the MC68341 to a Device in Single-Address Mode

66. X1 and BSW Input Levels

On page 12-5, the Clock Input High Voltage spec also applies to the BSW input.

67. Operating IDD Limits

On page 12-5, the spec operating (RUN) currents are shown.

Product	Frequency	Max Idd
68341FT16V	16.78MHz	95mA@3.6V
68341FT16	16.78MHz	150mA@5.25V
68341FT25	25.16MHz	210mA@5.25V

68. Input Clock Duty Cycle in External

On page 12-7, External Clock With PLL Mode: The input clock mode can be used when the VCO is not turned off during the input clock is used for clocking the SIM, and must be used in External Clock Mode Without PLL.

69. Clock Skew Notes

On page 12-7, External Clock With PLL Mode, Clock Input to CLKIN.

edges of the clock signals - the PLL phase locks the fall

70. Data Setup Time for 3.3V

On page 12-9, electrical specification #27 (Data Setup) changed from 5ns to 8ns.

71. \overline{UWE} and \overline{LWE} Signals

In Figure 12-3 on page 12-12, \overline{UWE} and \overline{LWE} will assert in the fast termination write cycle in Figure 12-5 on page 12-12 like \overline{DS} .

72. Serial Module Specs

Note 1 on page 12-25 should reference synchronous operation.

73. Ordering Information

Replace the the ordering information table in Section 11

Supply Voltage	Package Type	Frequency (MHz)
5.0 V	Plastic Quad Flat Pack FT Suffix	0 – 25
5.0 V	Plastic Quad Flat Pack FT Suffix	0 – 16.7
3.3 V	Plastic Quad Flat Pack FT Suffix	0 – 16.7

74. Upper and Lower Data Strobes

In paragraph 3.2.8 page 3-6, change (D15–D0) to (D15–D0).

75. Figure 3-2

Change Note 1 to reference MC68341 instead of MC68000.

76. Figure 4-8

The Periodic Interrupt Control Register (PICR) and Periodic Interrupt Control Register (PICR) instead of 2 bytes. Disregard the Scale Select Register.

77. Page 4-24

Refer to 4-17 for more information on the AVEC-Automata.

78. Page 4-48

The label at the start of the code should be INIT341 instead of INIT341.

79. Page 6-5, Paragraph 6.3.1.2

The table reference in the last sentence should be 6-4 instead of 6-5.

80. Page 9-19,

The timing diagrams reference as Figures 9-24 — 9-27.

81. Page 9-29, DT–Delay

A value of 1 enables this bit and 0 disables it.

82. Package Dimensions

The package dimension drawing on page 13-3 should be 13-3.

Motorola reserves the right to make changes without further notice to any product or the suitability of its products for any particular purpose, nor does Motorola assume specifically disclaims any and all liability, including without limitation consequential or incidental damages. All operating parameters, including "Typicals" must be validated for your application by testing your product. Motorola does not warrant that the product is suitable for use in any application without further testing. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not intended for surgical implant into the body, or other applications intended to support or sustain life, or for use in any application where failure of the product could create a situation where personal injury or death may occur. If you are using Motorola products in any application where failure of the product could create a situation where personal injury or death may occur, you shall indemnify and hold Motorola and its office, agents, distributors, and authorized representatives harmless for any and all damages, costs, damages, and expenses, and reasonable attorney fees arising out of, in connection with, or under any patent infringement suit (including reasonable attorney fees) for which Motorola may become liable in any way due to or arising out of the use of the product. Motorola is an Equal Opportunity/Affirmative Action Employer. Minorities and women are encouraged to apply. Motorola and the Motorola logo are registered trademarks of Motorola, Inc. Motorola, Inc. is an Equal Opportunity/Affirmative Action Employer.

Literature Distribution Centers:

USA: Motorola Literature Distribution; P.O. Box 20912, Arizona 85036.
EUROPE: Motorola Ltd.; European Literature Centre; 88 Tanners Drive, Watlington, Oxford OX12 9BT, England.
JAPAN: Nippon Motorola Ltd.; 4-32-1, Nishi-Gotanda, Shinagawa-ku, Tokyo 108, Japan.
ASIA-PACIFIC: Motorola Semiconductors H.K. Ltd.; Silicon Harbour Centre, 1001, Nathan Road, Suite 1001, Hong Kong.

SEMICONDUCTOR PRODUCT

**For More Information On This Product,
Go to: www.freescale.com**